



Overview: Part of spill impact on 16inch Egbema Assa Pipeline at Etekwuru.
Picture was taken during Joint Investigation of 14th May 2021.



Close-up: 2inch ball valve installed at 12 o'clock position on 16inch Egbema Assa Pipeline at Etekwuru. Picture was taken during Joint Investigation of 14th May 2021.