



Overview: Part of spill impact on 4inch Yokri Well 111T Flowline at Yokri .
Picture was taken during Joint Investigation of 18th May 2021.



Close-up: Pinhole at 7 o'clock position on 4inch Yokri Well 111T Flowline at Yokri . Picture was taken during Joint Investigation of 18th May 2021.