



Overview: Part of spill impact on 16inch Egbema Assa Pipeline at Obile.  
Picture was taken during Joint Investigation of 20<sup>th</sup> May 2021.



Close-up: 3inch and 2inch ball valves installed at 12 o'clock position on 16inch Egbema Assa Pipeline at Obile. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2021.