



Overview: Part of spill impact on 16inch Egbema Assa Pipeline at Obile.  
 Picture was taken during Joint Investigation of 21<sup>st</sup> May 2021.



Close-up: 4inch ball valve installed at 12 o'clock position on 16inch Egbema Assa Pipeline at Obile.  
 Picture was taken during Joint Investigation of 21<sup>st</sup> May 2021.