



Overview: Overview of incident environment of 4inch Obele Well 3L flowline at Obele
Picture was taken during Joint Investigation of 7th May 2021.



Close-up: Pinhole on 4inch Obele Well 3L flowline at Obele
Picture was taken during Joint Investigation of 7th May 2021.