



Overview: Part of spill impact on 16inch Egbema Assa Pipeline at Obiakpu.
Picture was taken during Joint Investigation of 1st June 2021.



Close-up: 2inch valve installed at 12 o'clock position on 16inch Egbema Assa Pipeline at Obiakpu.
Picture was taken during Joint Investigation of 1st June 2021.