



Overview: Part of spill impact on 36inch Rumuekpe Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 24th May 2021.



Close-up: 2inch valve crude oil theft point at 12 o'clock position on 36inch Rumuekpe Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 24th May 2021.