



Overview: Part of spill impact on 20'' Rumuekpe Nkpoku Pipeline at Adanta Isiokpo.  
Picture was taken during Joint Investigation of 3<sup>rd</sup> November 2021.



Close-up: 6''x 4'' ball valve installed at 12 o'clock position and fitted to 4'' extension pipe on 20'' Rumuekpe Nkpoku Pipeline at Adanta Isiokpo.  
Picture was taken during Joint Investigation of 2<sup>nd</sup> November 2021.