



Overview: Part of spill impact on 28" Ogale_Bomu Pipeline at Agbonchia.
 Picture was taken during Joint Investigation of 5th November 2021.



Close-up: Plugged 2inch nipple installed at 12 o'clock position on 28" Ogale_Bomu Pipeline at Agbonchia. Picture was taken during Joint Investigation of 5th November 2021.