



Overview: Part of spill impact on 8" Isimiri Deliveryline at Obiakpu. Picture was taken during Joint Investigation of 16th November 2021.



Close-up: 2inch nipple installed at 9 o'clock position on 8" Isimiri Deliveryline at Obiakpu. Picture was taken during Joint Investigation of 16th November 2021.