



Overview: Part of spill impact on 16" NunRiver - Kolokreek Pipeline at Aguobiri. Picture was taken during Joint Investigation of 16th November 2021.



Close-up: Plugged 4inch flange installed at 12 o'clock position on 16" NunRiver - Kolokreek Pipeline at Aguobiri. Picture was taken during Joint Investigation of 16th November 2021.