



Overview: Part of spill impact on 4" Obelle Ibaa Deliveryline at Ibaa. Picture was taken during Joint Investigation of 12th November 2021.



Close-up: Hack saw cut at 6 o'clock position with an arc distance of 90mm on 4" Obelle Ibaa Deliveryline at Ibaa. Picture was taken during Joint Investigation of 12th November 2021.