



Overview: Part of spill impact on 28" Ogale Bomu Pipeline at Nonkpor\_Bara-Ale. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2021.



Close-up: Inward dent with thin hole at 12 o'clock position on 28" Ogale Bomu Pipeline at Nonkpor\_Bara-Ale. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2021.