



Overview: Part of spill impact on 18" Assa Rumuekpe Pipeline at Umuodibe. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 18" Assa Rumuekpe Pipeline at Umuodibe. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2021.