



Overview: Part of spill impact on 18" Assa Rumuekpe Pipeline at Umudioga.
Picture was taken during Joint Investigation of 7th November 2021.



Close-up: Crude oil theft point and tampered area on 18" Assa Rumuekpe Pipeline at Umudioga.
Picture was taken during Joint Investigation of 7th November 2021.