



Overview: Part of spill impact on 12" Imo river 1- Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation of 19th October 2021.



Close-up: 5mm smooth round edge hole at 12 o'clock position on 12" Imo river 1- Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation of 19th October 2021.