



Overview: Part of spill impact on 20" Rumuekpe Nkpoku Pipeline at Adanta_Isiokpo. Picture was taken during Joint Investigation of 16th October 2021.



Close-up: 4inch Ball valve installed at 12 o'clock position on 20" Rumuekpe Nkpoku Pipeline at Adanta_Isiokpo. Picture was taken during Joint Investigation of 16th October 2021.