



Overview: Part of spill impact on 18" Assa Rumuekpe Pipeline at Awara.
Picture was taken during Joint Investigation of 24th October 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 18" Assa Rumuekpe Pipeline at Awara.. Picture was taken during Joint Investigation of 24th October 2021.