



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation of 28<sup>th</sup> October 2021.



Close-up: Plugged 40mm smooth round edge hole at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation of 28<sup>th</sup> October 2021.