



Overview: Part of spill impact on Ajatiton Well 1L Flowline at Ajatiton.
Picture was taken during Joint Investigation of 5th November 2021.



Close-up: Leak point : Hook up arm on Ajatiton Well 1L Flowline at Ajatiton.
Picture was taken during Joint Investigation of 5th November 2021.