



Overview: Part of spill impact on 20" Trans Escravos Pipeline at Ugboegungun.
Picture was taken during Joint Investigation of 24th September 2021.



Close-up: Pin hole at 9 o'clock position on 20" Trans Escravos Pipeline at Ugboegungun.
Picture was taken during Joint Investigation of 24th September 2021.