



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation of 28th September 2021.



Close-up: Plugged round edge hole at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation of 28th September 2021.