




Overview: Part of spill impact on 28" Trans Niger Pipeline at Agba-Okwan Asarama .
 Picture was taken during Joint Investigation of 19th September 2021.



Close-up: 2-3mm pin hole at 11 o'clock position on 28" Trans Niger Pipeline at Agba-Okwan Asarama .Picture was taken during Joint Investigation of 24th September 2021.