



Overview: Part of spill impact on 28" Nkpoku Bomu Pipeline at Eteo.  
 Picture was taken during Joint Investigation of 19<sup>th</sup> September 2021.



Close-up: 2nos of 2inch nipple installed at 12 o'clock position on 28" Nkpoku Bomu Pipeline at Eteo.  
 Picture was taken during Joint Investigation of 19<sup>th</sup> September 2021.