



Overview: Part of spill impact on 4" Obele Ibaa Delivery line at Ibaa.
Picture was taken during Joint Investigation of 29th September 2021.



Overview (Excavated spill point) :
Part of spill impact on 4" Obele Ibaa Delivery line at Ibaa.
Picture was taken during Joint Investigation of 29th September 2021.



Close-up: Hacksaw cut at 9-11 o'clock position on 4" Obele Ibaa Delivery line at Ibaa. Picture was taken during Joint Investigation of 29th September 2021.