



Overview: Part of spill impact on 20" Kolocreek – Rumuekpe Pipeline at Okoma .  
Picture was taken during Joint Investigation of 1<sup>st</sup> October 2021.



Close-up: 4" ball valve installed at 12 o'clock position on 20" Kolocreek – Rumuekpe Pipeline at Okoma . Picture was taken during Joint Investigation of 1<sup>st</sup> October 2021.