



Overview: Part of spill impact on 16" Nun River Kolocreek Pipeline at Aguobiri. Picture was taken during Joint Investigation of 7th September 2021.



Close-up: Plugged 3inch nipple installed at 12 o'clock position on 16" Nun River Kolocreek Pipeline at Aguobiri. Picture was taken during Joint Investigation of 7th September 2021.