



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 10<sup>th</sup> September 2021.



Close-up: 70mm Hacksaw cut at 9 o'clock position on 14" Okordia Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 10<sup>th</sup> September 2021.