



Overview: Part of spill impact on 36" Rumuekpe Nkpoku Pipeline at Mbodo-Aluu. Picture was taken during Joint Investigation of 28th Septemeber 2021.



Close-up: 2inch ball valve installed at 12 o'clock position on 36" Rumuekpe Nkpoku Pipeline at Mbodo-Aluu. Picture was taken during Joint Investigation of 28th September 2021.