




Overview: Part of spill impact on 24" Trans Ramos Pipeline Right of Way at Odimodi. Picture was taken during Site Visit of 21st September 2016.



Close-up: Inward dent on 24" Trans Ramos Pipeline at Odimodi. Picture was taken during Joint Investigation of 21st September 2016.