



Overview: Part of spill impact on 8" Nkali pipeline right of way at Umuedeokwara. Picture was taken during Joint Investigation of 13th April 2013.



Close up: Illegal fittings on 8" Nkali pipeline at Umuedeokwara. Picture was taken during Joint Investigation of 13th April 2013.