



Overview: Part of spill impact on Imo River 4" Well64L flowline right of way at Igiriukwu. Picture was taken during Joint Investigation of 3rd April 2013.



Close up: Cut section on Imo River 4" Well64L flowline at Igiriukwu. Picture was taken during Joint Investigation of 3rd April 2013.