



Overview: Part of spill impact on 6" Adibawa North East bulkline right of way at Biseni. Picture was taken during Joint Investigation of 30th April 2013.



Close up: Hacksaw cut on 6" Adibawa North East bulkline at Biseni. Picture was taken during Joint Investigation of 30th April 2013.