



Overview: Part of spill impact on 30" NembeCreek pipeline right of way at Bille. Picture was taken during Joint Investigation of 30th April 2013.



Close up: Illegal fitting on 30" NembeCreek pipeline at Bille. Picture was taken during Joint Investigation of 30th April 2013.