




Overview: Part of spill impact on 8" Isimiri-Imogate Pipeline at Obiakpu. Picture was taken during Joint Investigation of 10th April 2018.



Close-up: Drilled Hole on 8" Isimiri-Imogate Pipeline at Obiakpu Picture was taken during Joint Investigation of 10th April 2018.