



Overview: Part of spill impact on 16" Egbema-Assa Pipeline at Ekugba. Picture was taken during Joint Investigation of 5th May 2018.



Close-up: Illegal Fitting on 16" Egbema-Assa Pipeline at Ekugba. Picture was taken during Joint Investigation of 5th May 2018.