



Overview: Part of spill impact on 24" Alakiri-Bonny pipeline right of way at Ilomaturu. Picture was taken during Joint Investigation of 29th August 2013.



Close up: Hole due to corrosion on 24" Alakiri-Bonny pipeline at Ilomaturu. Picture was taken during Joint Investigation of 29th August 2013.