



Overview: Part of spill impact on 10" Diebu Creek – Nun River Pipeline Right of Way at Ekowe. Picture was taken during Joint Investigation of 10th September 2014.



Close-up: Hacksaw cut on 10" Diebu Creek – Nun River Pipeline Right of Way at Ekowe. Picture was taken during Joint Investigation of 10th September 2014.