



Overview: Part of spill impact on 8" Obigbo North - New Eelenwo at Umukolobe.
Picture was taken during Joint Investigation of 8th August 2014.



Close-up: Illegal fitting on 8" Obigbo North - New Eelenwo at Umukolobe . Picture was taken during Joint Investigation of 8th August 2014.