



|  |  |                  |                     |
|--|--|------------------|---------------------|
|  |  | E 6.558180       | Date 2014/08/20     |
|  |  | N 4.947248       | Time 13:27:34 (UTC) |
|  |  | Altitude 7.600 M | Speed 0.08 KPH      |

Overview: Spill impact on 20" Kolo Creek - Rumuekpe Pipeline at Aminigboko. Picture was taken during Joint Investigation of 20<sup>th</sup> August 2014.



|  |  |                  |                     |
|--|--|------------------|---------------------|
|  |  | E 6.558146       | Date 2014/08/20     |
|  |  | N 4.947233       | Time 13:25:17 (UTC) |
|  |  | Altitude 9.200 M | Speed 0.06 KPH      |

Close-up: Failed Clamp on 20" Kolo Creek - Rumuekpe Pipeline at Aminigboko. Picture was taken during Joint Investigation of 20<sup>th</sup> August 2014.