


Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 21<sup>st</sup> August 2014.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 21<sup>st</sup> August 2014.