



**Overview:** Part of spill impact on 20" Opukushi-Brass Creek Pipeline at Peretourgbene. Picture was taken during Joint Investigation of 7<sup>th</sup> August 2014.



**Close-up:** Illegal fitting on 20" Opukushi-Brass Creek Pipeline at Peretourgbene. Picture was taken during Joint Investigation of 7<sup>th</sup> August 2014.