



Overview: Part of spill impact on Umuechem Well 12L flowline at Umuechem. Picture was taken during Joint Investigation of 15th Dec. 2012.



Close-up: Hacksaw cut on Umuechem Well 12L flowline at Umuechem. Picture was taken during Joint Investigation of 15th Dec. 2012.