



Overview: Burnt vegetation on 28" Nkpoku-Bomu Pipeline Right of Way at Gio. Picture was taken during Joint Investigation of 2<sup>nd</sup> December 2014.



Close-up: Spill due to drilled hole on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 2<sup>nd</sup> December 2014.