



12/12/2014 1:45:26 PM (+1.0 hrs) Lat=5.44732 Lon=5.24739 Alt=72ft MSL WGS 84

Overview: Part of spill impact on 6" Yokri Manifold8 Test Flowline Right of Way at Yokri. Picture was taken during Joint Investigation of 12th December 2014.



12/12/2014 3:19:23 PM (+1.0 hrs) Lat=5.44741 Lon=5.24721 Alt=62ft MSL WGS 84

Close-up: Spill due to pinhole leak on 6" Yokri Manifold8 Test Flowline at Yokri. Picture was taken during Joint Investigation of 12th December 2014.