



Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at KomKom. Picture was taken during Joint Investigation of 28th December 2014.



Close-up: Illegal fittings on 12" Imo River – Ogale Pipeline at KomKom. Picture was taken during Joint Investigation of 29th December 2014.