




Overview: Part of spill impact on 28" Bomu-Bonny Pipeline at Okolomabio-Oloma. Picture was taken during Joint Investigation of 7th December 2016.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Okolomabio-Oloma. Picture was taken during Joint Investigation of 8th December 2016.