



Overview: Spill within cofferdam on 28" Bomu-Bonny Pipeline Right of Way at Bodocity. Picture was taken during Joint Investigation of 24<sup>th</sup> December 2016.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Bodocity. Picture was taken during Joint Investigation of 24<sup>th</sup> December 2016.