



Overview: Part of spill impact on 8" Umuechem-Nkpoku pipeline right of way at Omunwei. Picture was taken during Joint Investigation of 9th February 2013.



Close up: Illegal fittings on 8" Umuechem-Nkpoku pipeline at Omunwei. Picture was taken during Joint Investigation of 9th February 2013.