



Overview: Part of spill impact on 12" Imo River – Ogale pipeline right of way at Uzuaku. Picture was taken during Joint Investigation of 23<sup>rd</sup> February 2013.



Close up: Illegal fitting on 12" Imo River – Ogale pipeline at Uzuaku. Picture was taken during Joint Investigation of 23<sup>rd</sup> February 2013.